



# 轮毂单元

Automotive Bearings



四川省优迈特机械有限公司

Sichuan Mighty Machinery Co., Ltd.



**Sichuan Mighty Machinery Co., Ltd**

Tel: +86 28 8673 6779 Web: [www.sibearing.com](http://www.sibearing.com)

## Automotive Bearings

### 輪轂單元

| BCA    | SKF            | TIMKEN | Car Model               |
|--------|----------------|--------|-------------------------|
| 512000 | BR930053       | 512000 | Saturn S Series         |
| 512001 | BR930070       | 512001 | Buick Skylark           |
| 512003 | BR930074       | 512003 | Buick Lesabre           |
| 512004 | BR930096       | 512004 | Buick Regal             |
| 512009 | GRW168         | 512009 | Lexus ES250             |
| 512010 | BR930038       | 512010 | Eagle Talon             |
| 512016 | BR930130       | 512016 | Nissan Stanza           |
| 512018 | BR930336       | 512018 | GEO Prizm               |
| 512020 | BR930126       | 512020 | Honda Accord            |
| 512022 | BR930183       | 512022 | Honda Prelude           |
| 512023 | BR930196       | 512023 | Dodge/Plymouth Neon     |
| 512025 | BR930134       | 512025 | Nissan Sentra           |
| 512029 | BR930188 / 189 | 512029 | Chrysler Concorde       |
| 512030 | BR930188       | 512030 | Chrysler/Dodge Intrepid |
| 512033 | BR930059       | 512033 | Dodge/Plymouth Colt     |
| 512078 | BR930078       | 512078 | Buick Century           |
| 512106 | BR930106       | 512106 | Ford Taurus             |
| 512107 | BR930107       | 512107 | Ford Taurus             |
| 512118 | BR930118       | 512118 | Ford Probe              |
| 512119 | BR930119       | 512119 | Ford Probe              |
| 512133 | BR930176       | 512133 | Chrysler Cirrus         |
| 512136 | BR930172       | 512136 | Chrysler Sebring        |
| 512148 | BR930271       | 512148 | Dodge/Plymouth Colt     |
| 512149 | BR930223       | 512149 | Ford Windstar           |
| 512150 | BR930075       | 512150 | Buick Century           |
| 512151 | BR930145       | 512151 | Buick Century           |
| 512152 | BR930098       | 512152 | Chevy Fleet Classic     |
| 512154 | BR930194       | 512154 | Chrysler Cirrus         |
| 512155 | BR930069       | 512155 | Chrysler Town Country   |
| 512156 | BR930067       | 512156 | Chrysler Town Country   |
| 512157 | BR930066       | 512157 | Chrysler Town & Country |
| 512160 | BR930273       | 512160 | Hyundai Elantra         |



**Sichuan Mighty Machinery Co., Ltd**

Tel: +86 28 8673 6779 Web: [www.sibearing.com](http://www.sibearing.com)

| BCA    | SKF       | TIMKEN   | Car Model               |
|--------|-----------|----------|-------------------------|
| 512161 | BR930243  | 512161   | Ford Escort             |
| 512162 | BR930222  | 512162   | Ford/Mercury Taurus     |
| 512163 | BR930366  | 512163   | Ford/Mercury Taurus     |
| 512164 | BR930106  | 512164   | Ford/Mercury Taurus     |
| 512167 | BR930173  | 512167   | Chrysler PT Cruiser     |
| 512169 | BR930278  | 512169   | Chrysler Town & Country |
| 512170 | BR930279  | 512170   | Chrysler Town & Country |
| 512176 | BR930167  | 512176   | Honda Accord            |
| 512178 | BR930276  | 512178   | Honda Accord            |
| 512179 | BR930071  | 512179   | Acura                   |
| 512180 | BR930159  | 512180   | Honda Odyssey           |
| 512191 | BR930253  | 512191   | KIA Magentis & Optima   |
| 512193 | BR930280  | 512193   | Hyundai Accent          |
| 512194 | BR930262  | 512194   | Hyundai Elantra         |
| 512195 | BR930260  | 512195   | Hyundai Elantra         |
| 512200 | BR930165  | 512200   | KIA Sephia              |
| 512201 | BR930362  | 512201   | Nissan Altima           |
| 512202 | BR930362  | 512202   | Nissan Altima           |
| 512203 | BR930403  | 512203   | Infiniti I30            |
| 512206 | BR930267  | HA592460 | Toyota Camry            |
| 512207 | BR930266  | HA592450 | Toyota Camry            |
| 512218 | BR930329  | 512218   | Toyota Matrix           |
| 512220 | BR930199  | 512220   | Chrysler Cirrus         |
| 512229 | BR930327  | 512229   | Chevy Equinox           |
| 512230 | BR930328  | 512230   | Chevy Equinox           |
| 512237 | BR930075  | 512237   | Buick Century           |
| 512244 | BR930075  | HA590073 | Buick Allure            |
| 512303 | BR930379  | HA590110 | Nissan Sentra           |
| 513012 | BR930093  | 513012   | Buick Skyhawk           |
| 513013 | BR930052K | 513013   | Buick Riviera           |
| 513018 | BR930026  | 513018   | Buick Century           |
| 513030 | BR930043  | 513030   | Ford Escort             |
| 513033 | BR930010  | 513033   | Acura Integra           |
| 513035 | BR930033  | 513035   | Honda Civic             |



**Sichuan Mighty Machinery Co., Ltd**

Tel: +86 28 8673 6779 Web: [www.sibearing.com](http://www.sibearing.com)

| BCA    | SKF                                | TIMKEN             | Car Model               |
|--------|------------------------------------|--------------------|-------------------------|
| 513044 | BR930083K                          | 513044             | Buick Regal             |
| 513061 | BR930064                           | 513061             | Chevy/GMC S15 Jimmy     |
| 513062 | BR930068                           | 513062             | Buick Electra           |
| 513074 | BR930021K                          | 513074             | Chrysler Town & Country |
| 513075 | BR930013                           | 513075             | Chrysler Le Baron       |
| 513077 | BR930003                           | 513077             | Ford Thunderbird        |
| 513080 | BR930120                           | 513080             | Honda Acord Coupe       |
| 513081 | BR930124                           | 513081             | Honda Acord Coupe       |
| 513082 | BR930008                           | 513082             | Dodge Caravan           |
| 513087 | BR930076                           | 513087             | Buick Park Ave          |
| 513088 | BR930077                           | 513088             | Buick LeSabre           |
| 513089 | BR930190K                          | 513089             | Chrysler Concorde       |
| 513092 | BR930048                           | 513092             | Ford Thunderbird        |
| 513098 | FW156                              | 513098             | Acura                   |
| 513100 | BR930179                           | 513100             | Ford Taurus             |
| 513104 | BR930060                           | 513104             | Ford Crown Vic          |
| 513105 | BR930113                           | 513105             | Acura Integra           |
| 513109 | BR930045                           | 513109             | Dodge Viper             |
| 513115 | BR930250                           | 513115             | Ford Mustang            |
| 513121 | BR930148 Threaded<br>Hub/DR020548K | 513121             | Buick Century           |
| 513122 | BR930216                           | 513122             | Chrysler Town & Country |
| 513123 | BR930215                           | 513123             | Chrysler Prowler        |
| 513124 | BR930097                           | 513124             | Chevy/GMC               |
| 513137 | BR930080                           | 513137             | Chevy Fleet Classic     |
| 513138 | BR930138                           | 513138             | Chrysler Cirrus         |
| 513156 | BR930246                           | 513156             | Ford Windstar           |
| 513160 | BR930184                           | 513160             | Buick Century           |
| 513179 | BR930149/930548K                   | 513179             | Buick Century           |
| 513187 | BR930149/930548K                   | 513187             | Buick Rendevous         |
| 513193 | BR930308                           | 513193             | Chevy Tracker           |
| 513196 | BR930306                           | 513196             | Ford Crown Vic          |
| 513202 | BR930168 W/ABS                     | 513202             | Ford Crown Vic          |
| 513203 | BR930184                           | HA590076/ HA590085 | Buick Allure            |
| 513204 | BR930216                           | HA590068           | Chevy Colbalt           |



**Sichuan Mighty Machinery Co., Ltd**

Tel: +86 28 8673 6779 Web: [www.sibearing.com](http://www.sibearing.com)

| BCA    | SKF      | TIMKEN          | Car Model                 |
|--------|----------|-----------------|---------------------------|
| 513215 | BR930314 | HA590071        | Chevy Malibu              |
| 515000 | BR930116 | 515000          | Ford Aerostar             |
| 515001 | BR930094 | 515001          | Chevy/GMC All K Series    |
| 515002 | BR930035 | 515002          | Chevy/GMC K Series        |
| 515003 | BR930252 | SP450200        | Ford Explorer Sport       |
| 515004 | BR930208 | SP550201        | Ford Expedition           |
| 515006 | BR930256 | 515006          | Dodge R1500/W150          |
| 515007 | BR930207 | HA599361        | Dodge Dakota              |
| 515008 | BR930204 | SP450101        | Dodge Dakota              |
| 515009 | BR930205 | SP450100        | Dodge Dakota              |
| 515010 | BR930318 | SP550200        | Ford F150                 |
| 515011 | BR930400 | HA597851        | Dodge D250                |
| 515012 | BR930405 | HA590020        | Dodge D250                |
| 515013 | BR930343 | SP450201        | Ford Ranger               |
| 515015 | BR930406 | SP580302/580303 | Chevy/GMC 20/2500         |
| 515016 |          | SP580300        | Chevy/GMC 20/2500         |
| 515017 | BR930218 | 515017          | Ford F150                 |
| 515018 |          | HA591339        | Chevy/GMC                 |
| 515020 | BR930420 | 515020          | Ford F350                 |
| 515021 | BR930424 | 515021          | Ford F250                 |
| 515022 | BR930418 | 515022          | Ford F150                 |
| 515023 | BR930410 | SP550100        | Dodge R1500               |
| 515025 | BR930421 | 515025          | Ford F350/F450 Super Duty |
| 515026 | BR930341 | 515026          | Ford Ranger               |
| 515027 | BR930342 | 515027          | Ford Ranger               |
| 515029 | BR930423 | 515029          | Ford F150                 |
| 515030 | BR930419 | 515030          | Ford F150                 |
| 515031 | BR930236 | 515031          | Ford Expedition           |
| 515032 | BR930361 | HA599528        | Dodge Dakota              |
| 515033 | BR930360 | HA599406        | Dodge Dakota              |
| 515037 |          |                 | Chevy/GMC K3500           |
| 515038 | BR930305 | HA599863        | Dodge Ram                 |
| 515039 | BR930409 | SP550102        | Dodge Ram                 |
| 515041 | BR930406 | SP580302/580303 | Chevy/GMC K1500           |



**Sichuan Mighty Machinery Co, Ltd**

Tel: +86 28 8673 6779 Web: [www.sibearing.com](http://www.sibearing.com)

| BCA     | SKF       | TIMKEN    | Car Model           |
|---------|-----------|-----------|---------------------|
| 515042  | BR930457  | SP550206  | Ford Expedition     |
| 515048  |           |           | Chevy/GMC K1500     |
| 515049  | BR930415  | SP550101  | Dodge R1500         |
| 515050  | BR930456  | SP470201  | Ford Explorer       |
| 515051  | BR930345  | SP450203  | Ford Ranger         |
| 515052  | BR930452  | SP450202  | Ford Explorer Sport |
| 515054  |           | SP550306  | Chevy Silverado     |
| 515055  |           |           | Chevy/GMC K1500     |
| 515058  | BR930416  | SP580310  | Chevy Silverado     |
| 515061  | BR930502  | HA590032  | Dodge D250          |
| 515063  | BR930203  | HA590203  | Dodge D250          |
| 515072  | BR930284  | HA500100  | Dodge R1500         |
| 515073  | BR930285  |           | Dodge R1500         |
| 515084  | BR930611  | HA590001  | Dodge Ram 1500      |
| 518500  | BR930000  | 518500    | Chrysler LeBaron    |
| 518501  | BR930001  | 518001    | Chrysler E Class    |
| 518502  | BR930002  | 518502    | Chrysler E Class    |
| 518503  | BR930153K | 518503    | Ford Escort         |
| 518506  | BR930200K | 518506    | Toyota Camry        |
| 518507  | BR930300K | 518507    | Chevy Prizm         |
| 518510  | BR930263K | HA590263K | Ford Focus          |
| 520000  | BR930151K | 520000    | Ford Taurus         |
| 520100  | BR930152K | 520100    | Ford Taurus         |
| 521000  | BR930259K | 521000    | Ford Explorer       |
| 513011K | BR930091K | 513011K   | Buick Century       |
| 513016K | BR930022K | 513016K   | Buick Century       |



**SICHUAN MIGHTY MACHINERY CO.LTD.**

Add: No.2 Tongfu Alley, Xiyulong St., Chengdu 610015, P.R.China

Tel: 0086 28 86736779

Fax: 0086 28 86755074

Web: [www.sibearing.com](http://www.sibearing.com)

