



# 轮毂轴承

Hub Bearing



四川省优迈特机械有限公司  
Sichuan Mighty Machinery Co., Ltd.



Sichuan Mighty Machinery Co., Ltd

Tel: +86 28 8673 6779 Web: www.sibearing.com

**Hub bearing**  
**轮毂轴承**

| NO | 型号             | OE号            | Car model  |
|----|----------------|----------------|------------|
| 3  | ADG08207       | 51720-38110 S1 | HYUNDAI    |
| 4  | ADH28242       | 44300-SMG-G01  | HONDA      |
| 6  | DAC25520037    | 43210-AZ300    | NISSAN     |
| 10 | DAC25520042    | 46860-83E10    | SUZUKI     |
| 13 | DAC25550048    | 43210-1HM0A    | NISSAN     |
| 15 | DAC28580044    | 46860-63J00    | SUZUKI     |
| 16 | DAC29530037    | 1335383        | FORD       |
| 17 | DAC29530037    | D350-26-151B   | MAZDA      |
| 18 | DAC32670040    | 42300-S2L-004  | HONDA      |
| 19 | DAC32670040    | 42300-SAB-003  | HONDA      |
| 22 | DAC35620031    | 09267-35003    | SUZUKI     |
| 23 | DAC35620040    | 1A01-33-047    | MAZDA      |
| 24 | DAC35620040    | 40210-4A00G    | NISSAN     |
| 26 | DAC35620040    | 43440-84F00    | SUZUKI     |
| 28 | DAC35640037    | 3885A043       | MITSUBISHI |
| 29 | DAC35640037    | 40210-6A00A    | NISSAN     |
| 30 | DAC35640037    | 90043-63253    | TOYOTA     |
| 31 | DAC35640037    | 3885A039       | MITSUBISHI |
| 36 | DAC35770042    | 90903-63006    | TOYOTA     |
| 37 | DAC37680034    | MR410569       | MITSUBISHI |
| 39 | DAC37720037    | 40210-00QAA    | NISSAN     |
| 43 | DAC38700037    | 51720-29400    | HYUNDAI    |
| 45 | DAC38700038    | 90043-63213    | TOYOTA     |
| 47 | DAC38710033 30 | 90369-38006    | TOYOTA     |
| 48 | DAC38710039    | 90369-38021    | TOYOTA     |
| 49 | DAC38720040    | 44300-S0E-008  | HONDA      |
| 50 | DAC38720236 33 | 90363-38006    | TOYOTA     |
| 51 | DAC38730040    | 44300-S04-008  | HONDA      |
| 52 | DAC38740036    | 40210-WD200    | NISSAN     |
| 53 | DAC38740040    | 44300-TF0-951  | HONDA      |
| 54 | DAC38740050    | 40210-50A05    | NISSAN     |
| 55 | DAC38740236 33 | 1N00-33-047    | MAZDA      |



Sichuan Mighty Machinery Co., Ltd

Tel: +86 28 8673 6779 Web: www.sibearing.com

| NO  | 型号             | OE号           | Car model  |
|-----|----------------|---------------|------------|
| 56  | DAC38740236 33 | 40210-50Y00   | NISSAN     |
| 57  | DAC38740236 33 | 90369-38003   | TOYOTA     |
| 58  | DAC38760043    | 40210-AA000   | NISSAN     |
| 60  | DAC39720037    | 1146121       | FORD       |
| 61  | DAC39720037    | D351-33-047A  | MAZDA      |
| 62  | DAC39740036    | 51720-2D000   | HYUNDAI    |
| 63  | DAC39740039    | 1439607       | FORD       |
| 64  | DAC39740039    | 09267-39004   | HYUNDAI    |
| 67  | DAC40700043    | MB663547      | MITSUBISHI |
| 68  | DAC40720036    | 43440-54G02   | SUZUKI     |
| 71  | DAC40740036    | 3885A001      | MITSUBISHI |
| 72  | DAC40740036    | 43591-54J00   | SUZUKI     |
| 73  | DAC40740036 34 | MB808442      | MITSUBISHI |
| 77  | DAC40740042    | 90363-40066   | TOYOTA     |
| 78  | DAC40750037    | 5027620       | FORD       |
| 80  | DAC40750039    | 90363-W0005   | TOYOTA     |
| 81  | DAC40760038    | MR594080      | MITSUBISHI |
| 82  | DAC40800036 34 | 51720-34100   | HYUNDAI    |
| 83  | DAC40800038    | 1954476       | FORD       |
| 84  | DAC40800038    | 43210-42G10   | NISSAN     |
| 85  | DAC40800040    | MR491449      | MITSUBISHI |
| 89  | DAC42760038 35 | 40210-30R01   | NISSAN     |
| 91  | DAC42760039    | 52710-26530   | HYUNDAI    |
| 94  | DAC42780040    | 51720-2H000   | HYUNDAI    |
| 95  | DAC42780045    | 4086234       | FORD       |
| 96  | DAC42800038    | 5-86106-123-0 | ISUZU      |
| 97  | DAC42800038    | 43210-0W000   | NISSAN     |
| 99  | DAC42800045    | 0K9A2-33-047  | HYUNDAI    |
| 100 | DAC42800045    | BP4L-33-04    | MAZDA      |
| 104 | DAC43760043    | 40210-3Z000   | NISSAN     |
| 105 | DAC43770042 38 | 90369-43007   | TOYOTA     |
| 106 | DAC43780044    | 44300-SNA-951 | HONDA      |
| 107 | DAC43790041 38 | 44300-S04-A02 | HONDA      |
| 108 | DAC43790045    | 43210-AG000   | NISSAN     |



**Sichuan Mighty Machinery Co., Ltd**

Tel: +86 28 8673 6779 Web: [www.sibearing.com](http://www.sibearing.com)

| NO  | 型号             | OE号           | Car model  |
|-----|----------------|---------------|------------|
| 109 | DAC43800038    | 1001718       | FORD       |
| 114 | DAC43800040    | MN101347      | MITSUBISHI |
| 116 | DAC43800050 45 | 90369-43005   | TOYOTA     |
| 118 | DAC43820045    | 90369-43008   | TOYOTA     |
| 120 | DAC45820042    | 1668557       | FORD       |
| 122 | DAC45840039    | 43440-80J00   | SUZUKI     |
| 123 | DAC45840045    | BT4Z-1215-A   | FORD       |
| 125 | DAC45840045    | GP9A-33-047D  | MAZDA      |
| 126 | DAC45840045    | 90369-45003   | TOYOTA     |
| 128 | DAC45880039    | 40210-00Q0E   | NISSAN     |
| 131 | DAC47880055    | UM51-33-047   | MAZDA      |
| 132 | DAC47880055    | 1725902       | FORD       |
| 133 | DAC47880055    | UC3C-33-047B  | MAZDA      |
| 136 | DAC49840050    | 90369-49002   | TOYOTA     |
| 139 | DAC51910044    | 44300-SWW-E01 | HONDA      |
| 144 | DAC52910040    | 44300-TA0-A51 | HONDA      |
| 147 | DAC54960051    | 90369-54002   | TOYOTA     |
| 148 | DAC55900060    | 1346650080    | Lexus CT   |



**SICHUAN MIGHTY MACHINERY CO.LTD.**

Add: No.2 Tongfu Alley, Xiyulong St., Chengdu 610015, P.R.China

Tel: 0086 28 86736779

Fax: 0086 28 86755074

Web: [www.sibearing.com](http://www.sibearing.com)

